


SURFACE MAINTENANCE

FY-04 BEST MANAGEMENT PRACTICES



Water pump down:
1,264,000 gallons
Soil-floc added to
basin -3 gallons

Retention Basin




Applied this year:
Mulch - 43,870 yds³
Silt fencing – 100L feet
Tackifier -1,400 gal.
Soilfloc - 33,400 gal.

Slope Protection



Gabion channel placed.
500 linear ft
Rip-rap placed: 163 CY

Slope Stabilization



Installed 50 foot wide road
crossing with two 24 inch
HDPE pipes.
Rip-rap channel
placed: 340 ft

Drainage Mitigation